

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

AUG 22 2019

BRADENHEAD TEST REPORT

Operator Name BREITBURN OPERATING LP		30-025-08664	RECEIVED
Property Name CONE JALMAT YATES POOL UNIT		Well No. 702	

1 Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet from	E/W Line	County
B	25	22S	35E	660	N	1980	E	Lea

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	OIL	PRODUCER GAS	DATE 8-20-19
------------------	----	----------------	----	-----------------	-----	-----	-----------------	-----------------

OBSERVED DATA

	(AS Surface)	(B Pressure)	(C Pressure)	(D Pressure)	(E Pressure)
Pressure	0	0	N/A	0	800
Flow Characteristics					
Full	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Waterflood if
Water	Y/N	Y/N	Y/N	Y/N	applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Need to replace Int. csg. valve.

Signature:		OIL CONSERVATION DIVISION	
Printed name: Eddie Trujillo		Entered into RBDMS	
Title: Leadman		Re-test	
E-mail Address: eddie.trujillo@mavresources.com			
Date:	Phone: 575-399-3329		
Witness: <i>Eddie Trujillo</i>			

INSTRUCTIONS ON BACK OF THIS FORM