## **State of New Mexico**

## HOBBS OCD

**Energy, Minerals and Natural Resources Department** 

**BRADENHEAD TEST REPORT** 

Oil Conservation Division Hobbs District Office

AUG 2 4 2019

CHANCE PROPERTIES COMPANY  Property Name  LEA 20												
UL - Lot Section 20	Township 26-S					rom N/S Line		Feet From 330		E/W Line E	County LEA	
				V	Vell Status						<u> </u>	
TA'D Well		SHUT-IN			INJECTOR		]	PRODUCER		DATE		
YES O	) 4/1	MES N		NO INJ		SWD OIL		4	GAS		8/22/19	
	•			OBSI	ERVED DA	TA						
	(A)Su	rf-Interm	(B)Int	B)Interm(1)		(C)Interm(2)			(D)Prod Csng		(E)Tubing	
ressure	<u> </u>	0			<del>_</del>				0		0	
low Characteristics	<del></del>					_			<u> </u>		Shut in	
Puff	+	Y / 🔞		Y/N			Y/N			<del>9</del> / N	CO2	
Steady Flow	-	V/69		Y / N			Y / N		Y / 85°		WTR	
Surges	1	<del>Y / Ø</del>		Y / N		Y/N			Y /Ø		GAS	
Down to nothing	+	<b>₩</b> / N	+	Y	N	Y/N			6) / N		If applicable type	
Gas or Oil		Y / 🕅	+	Y/N		Y/N			Y/6		fluid injected for	
Water		Y/(Ŋ	+	Y / N		Y / N			Y / (y)		Waterflood	
Remarks: Please state f	or each stri	ing (A,B,C,D,I	E) pertin	ent info	rmation regard	ling blee	d down	or contin	uous buik	l up if applies		
ignature:								OI	L CONS	ERVATIO	N DIVISION	
rinted name:								Entere	d into RE	DMS		
itle:								Re-test	<u>;</u>		1	
-mail Address:									`,	X <	<u> T                                   </u>	
ate: 8/22/19		Phone:								<u> </u>		
		Witness KERRY FORTNER-OCD 575-399-3221										