

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 22 2019

BRADENHEAD TEST REPORT

RECEIVED

Operator Name BREITBURN OPERATING LP		API Number 30-025-38916	
Property Name CONE JALMAT YATES POOL UNIT		Well No. 127	

1 Surface Location

UL - Lot	Section	Township	Range	Feet from	NS Line	Feet from	E/W Line	County
J	13	22S	35E	1970	S	2062	E	Lea

Well Status

TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	INJECTOR ☒ INJ	SWD	OIL	PRODUCER GAS	DATE 8-20-19
------------------	-------------------------------------	----------------	-------------------------------------	--	-----	-----	-----------------	-----------------

OBSERVED DATA

	(A) Surface	(B) Interval (1)	(C) Interval (2)	(D) Prod. Csg.	(E) Tubing
Pressure	0	N/A	N/A	160	380
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR —
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

Need TRK on Prod. csg.
Prod. csg. blew to truck, wat to zero in 2 min.

Signature:		OIL CONSERVATION DIVISION	
Printed name: Eddie Trujillo		Entered into RBDMS	
Title: Leadman		Re-test	
E-mail Address: eddie.trujillo@mavresources.com			
Date:	Phone: 575-399-3329		
Witness: <i>Ray Holman</i>			

INSTRUCTIONS ON BACK OF THIS FORM