

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 22 2019

BRADENHEAD TEST REPORT

RECEIVED

Operator Name BREITBURN OPERATING LP	API Number 30-025-38917
Property Name CONE JALMAT YATES POOL UNIT	Well No. 128

2 Surface Location

UL - Lat I	Section 13	Township 22S	Range 35E	Feet from 1910	NS Line S	Feet from 725	EW Line E	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	---------------------	-------------------------	---------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR DU	SWD	OIL	PRODUCER GAS	DATE 8-20-19
-------------------------	-----------	-----------------------	-----------	-----------------------	-----	-----	------------------------	------------------------

OBSERVED DATA

	(A) Surface	(B) Interval I	(C) Interval II	(D) Interval III	(E) Testing
Pressure	0	N/A	N/A	0	500
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for water shut-off applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		OIL CONSERVATION DIVISION	
Printed name: Eddie Trujillo		Entered into RBDMS	
Title: Leadman		Re-test	
E-mail Address: eddie.trujillo@mavresources.com			
Date:	Phone: 575-399-3329		
	Witness: <i>[Signature]</i>		

INSTRUCTIONS ON BACK OF THIS FORM