

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

AUG 22 2019

BRADENHEAD TEST REPORT

BREITBURN OPERATING LP		30-025	RECEIVED 38 861
ENCORE M STATE		Well No.	001

Surface Location

UL - Lot	Section	Township	Range	Feet from	NS Line	Feet from	E/W Line	County
A	30	22	37	742	+294 N	1294	E	lea

Well Status

TA'D WELL	SHUT-IN	INJECTOR	PRODUCER	DATE
YES	NO	NO	YES	8-00-19

OBSERVED DATA

	(A) Surface	(B) (Control 1)	(C) (Control 2)	(D) (Control 3)	(E) (Control 4)
Pressure	0	0	N/A	0	0
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	logged for
Water	Y/N	Y/N	Y/N	Y/N	Water level if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Eddie Trujillo</i>	OIL CONSERVATION DIVISION
Printed name: Eddie Trujillo	Entered into RBDMS
Title: Leadman	Re-test
E-mail Address: eddie.trujillo@mavresources.com	
Date:	
Phone: 575-399-3329	
Witness: <i>Kerry Fortner - OCD</i>	

399-3221

INSTRUCTIONS ON BACK OF THIS FORM