

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

BREITBURN OPERATING LP		30-025-39751	
ENCORE M STATE		003	

Surface Location

UL - Lot C	Section 19	Township 22	Range 37	Foot From 660	NS Line N	Foot From 2140	E/W Line W	County Lea
---------------	---------------	----------------	-------------	------------------	--------------	-------------------	---------------	---------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR INJ	PRODUCER GAS	DATE 8-20-19
------------------	----------------	-----------------	-----------------	-----------------

OBSERVED DATA

	1A Surface	2B Intermediate	3C Intermediate	4D Prod Case	5E Tubing
Pressure	0	0	N/A	32	250
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Eddie Trujillo</i>	OIL CONSERVATION DIVISION
Printed name: Eddie Trujillo	Entered into RBDMS
Title: Leadman	Re-test
E-mail Address: eddie.trujillo@mavresources.com	
Date:	
Phone: 575-399-3329	
Witness: <i>Kerry Furber - o c d</i>	

399-3221

INSTRUCTIONS ON BACK OF THIS FORM