

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 22 2019

BRADENHEAD TEST REPORT

RECEIVED

BREITBURN OPERATING LP		30-025-40299	
ENCORE M STATE		005	

* Surface Location

UL - Lot A	Section 19	Township 22	Range 37	Feet from 639	NS Line N	Feet from 531	E/W Line E	County Lea
---------------	---------------	----------------	-------------	------------------	--------------	------------------	---------------	---------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR NO	PRODUCER GAS	DATE 8-20-19
------------------	----------------	----------------	-----------------	-----------------

OBSERVED DATA

	(A) Surface	(B) Interval 1	(C) Interval 2	(D) Prod Case	(E) Tubing
Pressure	20	N/A	N/A	40	350
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterhead if

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Eddie Trujillo</i>	OIL CONSERVATION DIVISION
Printed name: Eddie Trujillo	Entered into RBDMS
Title: Leadman	Re-test
E-mail Address: eddie.trujillo@mavresources.com	
Date:	
Phone: 575-399-3329	
Witness: <i>Kerry Fortner - OCD</i>	

399-3221

INSTRUCTIONS ON BACK OF THIS FORM