

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 22 2019

BRADENHEAD TEST REPORT

RECEIVED

Operator Name BREITBURN OPERATING LP		AP# Number 30-025-43444	
Property Name ENCORE M 21 FEE		Well No. 21-001	

2 Surface Location

UL - Lot L	Section 21	Township 22-S	Range 37-E	Feet from 2130	NS Line S	Feet from 660	E/W Line W	County Lea
----------------------	----------------------	-------------------------	----------------------	--------------------------	---------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	SHUT-IN NO	INJ NO	PRODUCER OIL	DATE 8-21-19
-------------------------	----------------------	------------------	------------------------	------------------------

OBSERVED DATA

	(A) Surface	(B) Interval (1)	(C) Interval (2)	(D) Prod Cons	(E) Testing
Pressure	0	0	N/A	65	260
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood if applicable
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Eddie Trujillo		OIL CONSERVATION DIVISION	
Printed name: Eddie Trujillo		Entered into RBDMS	
Title: Leadman		Re-test	
E-mail Address: eddie.trujillo@mavresources.com		X7	
Date:	Phone: 575-399-3329		
Witness: Kerry Fortner - OCD			

399-3221

INSTRUCTIONS ON BACK OF THIS FORM