

AUG 19 2019

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Oil Corp.		API Number 30-025-06727
Property Name North East Drinkard Unit (NEDU)		Well No. 806

1. Surface Location

UL - Lot B	Section 22	Township 21S	Range 37E	Feet from 660	N/S Line N	Feet from 1780	E/W Line E	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒	SHUT-IN YES ☒	INJECTOR ☒	SWD	PRODUCER OIL	GAS	DATE 7-18-19
---	---	--	-----	-----------------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	☒	—	—	☒	1090
Flow Characteristics					
Puff	Y / ☒	Y / N	Y / N	Y / ☒	CO2 —
Steady Flow	Y / ☒	Y / N	Y / N	Y / ☒	WTR ☒
Surges	Y / ☒	Y / N	Y / N	Y / ☒	GAS —
Down to nothing	Y / ☒	Y / N	Y / N	Y / ☒	Type of fluid injected for waterflood if applies
Gas or Oil	Y / ☒	Y / N	Y / N	Y / ☒	
Water	Y / ☒	Y / N	Y / N	Y / ☒	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Tracy Cole		OIL CONSERVATION DIVISION	
Printed name: Tracy Cole		Entered into RBDMS	
Title:		Re-test	
E-mail Address:		X	
Date: 7-18-19	Phone: 575-441-5196		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM