

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name BREITBURN OPERATING LP		APY Number 30-025-36997
Property Name JALMAT FIELD YATES SAND UNIT		Well No. 212

Surface Location

UL - Lot	Section	Township	Range	Feet from	NS Line	Feet from	E/W Line	County
D	23	22	35	660	N	990	W	Lea

Well Status

TA'D WELL YES	SHUT-IN NO	INJECTOR NO	SWD NO	OIL NO	PRODUCER NO	GAS NO	DATE 8-21-19
-------------------------	----------------------	-----------------------	------------------	------------------	-----------------------	------------------	------------------------

OBSERVED DATA

	(A) Surface	(B) Interval 1	(C) Interval 2	(D) Prod. Cons.	(E) Tubing
Pressure	7	N/A	N/A	0	1200
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR —
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Subjected for Waterflood if applies.
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each saving (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

HOBBS OCD

AUG 23 2019

RECEIVED

MIT

Signature: Eddie Trujillo		OIL CONSERVATION DIVISION	
Printed name: Eddie Trujillo		Entered into RBDMS	
Title: Leadman		Re-test X7	
E-mail Address: eddie.trujillo@mavresources.com			
Date:	Phone: 575-399-3329		
Witness: Kerry Fortner - OCD			

399-3221

INSTRUCTIONS ON BACK OF THIS FORM