

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

**BRADENHEAD TEST REPORT**

Operator Name BREITBURN OPERATING LP		API Number 30-025- 08644
Property Name CONE JALMAT YATES POOL UNIT		Well No. 202

**Surface Location**

UL - Lot B	Section 24	Township 22S	Range 35 E	Feet from 660	N/S Line N	Feet From 1980	E/W Line E	County Lea
---------------	---------------	-----------------	---------------	------------------	---------------	-------------------	---------------	---------------

**Well Status**

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	PRODUCER OIL	GAS	DATE 8-20-19
------------------	----	----------------	----	-----------------	-----	-----------------	-----	-----------------

**OBSERVED DATA**

	(A) Surface	(B) Interval (1)	(C) Interval (2)	(D) Prod Casing	(E) Tubing
Pressure	0	0	N/A	300	300
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR —
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applicable
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

MIT  
Failed MIT  
Tbs + Csg. ejected

Signature:		OIL CONSERVATION DIVISION	
Printed name: Eddie Trujillo		Entered into RBDMS	
Title: Leadman		Re-test	
E-mail Address: eddie.trujillo@mavresources.com			
Date:	Phone: 575-399-3329		
Witness: <i>[Signature]</i>			

INSTRUCTIONS ON BACK OF THIS FORM