

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name BREITBURN OPERATING LP		API Number 30-025-08649	
Property Name CONE JALMAT YATES POOL UNIT		Well No. 110	

1. Surface Location

UL - Lot E	Section 24	Township 22 S	Range 35 E	Feet from 1980	N/S Line N	Feet from 1980	E/W Line W	County Lea
----------------------	----------------------	-------------------------	----------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR NO	SWD	OIL	PRODUCER GAS	DATE 8-19-19
-------------------------	-----------	-----------------------	-----------	-----------------------	-----	-----	------------------------	------------------------

OBSERVED DATA

	(A) Surface	(B) Intermed I	(C) Intermed 2	(D) Prod Casing	(E) Tubing
Pressure	0	N/A	N/A	0	800
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR —
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

M/T *Failed MIT - Tried 2 Test - both would not hold pres. Well was shut in. charts are in well file.*

Signature:		OIL CONSERVATION DIVISION	
Printed name: Eddie Trujillo		Entered into RBDMS	
Title: Leadman		Re-test W	
E-mail Address: eddie.trujillo@mavresources.com			
Date:	Phone: 575-399-3329		
Witness: <i>Gregory Johnson</i>			

INSTRUCTIONS ON BACK OF THIS FORM