

HOBBS OCD

AUG 26 2019

RECEIVED

District I
1001 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

30-025-10448

Operator Name Kaiser Francis Oil Company	API Number 8/20/19
Property Name Danglade	Well No. #1

Surface Location								
UL - Lot B	Section 24	Township 22	Range 37	Feet from 660	N/S Line N	Feet from 1980	E/W Line E	County Lea

Well Status	
TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO
INJ NO	PRODUCER YES
DATE 8/20/19	

OBSERVED DATA

	(A) Surface	(B) Interm 1	(C) Interm 2	(D) Prod Csg	(E) Tubing
Pressure	2#	50		35 #	100#
Flow Characteristics		GAS ONLY		GAS	
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid injected for Waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Interm 1 - 50# 1 Blow down in 5 minutes to 0#
No fluids come out.

Signature:	OIL CONSERVATION DIVISION
Printed name: Ramon Rodriguez	Entered into RBDMS
Title: Field Foreman	Re-test
E-mail Address: ramonr@kfcl.net	
Date: 8/20/19	
Phone: 806 435 0338	
Witness:	