

Dundell
1625 W. French Dr., Hobbs, NM 88250
Phone (505) 351-6161 Fax (505) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Rover Operating, LLC	API Number 30-025-00535
Property Name Malmac Unit	Well No. #108

2. Surface Location

UL - Lot H	Section 13	Township 17S	Range 32E	Feet from 1980	N/S Line N	Feet from 660	E/W Line E	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	NO NO	YES YES	SHUT-IN NO	INJ INJ	INJECTOR NO	SWD NO	OIL NO	PRODUCER NO	GAS NO	DATE 8-8-19
-------------------------	-----------------	-------------------	----------------------	-------------------	-----------------------	------------------	------------------	-----------------------	------------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	N/A	N/A	0	1800
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for water flood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Oil Injection line repairs

Signature: [Signature]	OIL CONSERVATION DIVISION
Printed name: Kirk Emery	Entered into RBDMS [Signature]
Title: Foreman	Re-test
E-mail Address: KEmery@RoverPetroleum.com	
Date: 8-8-19	
Phone: [Signature]	
Witness: [Signature]	

INSTRUCTIONS ON BACK OF THIS FORM