HORES				
HOBES OCD				
	IZAY 0 2 21	Díg		
Submit One Copy To Appropriate District State of New Mex Office Energy, Minerals and Natur 1625 N. French Dr., Hobbs, NM 88240 State of New Mex	XIORECEUM		Form C-103	
District 1 Energy, Minerals and Natur 1625 N. French Dr., Hobbs, NM 88240	al Resources/V	WELL API NO.	Revised November 3, 2011	
District II 811 S First St., Artesia, NM 88210 OIL CONSERVATION		<u>3D-02</u> 5. Indicate Type	5-01411	
District III 1220 South St. Francis Dr.		S. mulcale Type STATE	FEE K	
District IV Santa Fe, NM 87505 1220 S. St Francis Dr., Santa Fe, NM		6. State Oil & G		
87505 SUNDRY NOTICES AND REPORTS ON WELLS			552 or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		NORTH HORBS (GSA) UNIT		
1. Type of Well: Oil Well Gas Well Other		8. Well Number 311		
2. Name of Operator DCCIDENTAL FERMIAN, LTD.		9. OGRID Num	157984	
3. Address of Operator		10. Pool name or Wildcat		
P.D. Box 4294, HOUSTON, TX, 77210		Hobes (GSA)		
4. Well Location Unit Letter B: 1315 feet from the N line and 231D feet from the E line				
Section <u>28</u> Township <u>185</u> Range <u>38E</u> NMPM <u>LEA</u> County				
11. Elevation (Show whether DR.) 3650' (DF)	RKB, RT, GR, etc.)			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WORK ALTERING CASING				
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRIL		PANDA	
		_		
OTHER: I Location is ready for OCD inspection after P&A A A A A A A A A A A A A A A A A A A				
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4" above ground level has been set in concrete. It shows the				
BELOW				
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/OUARTER LOCATION OR</u> UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and				
other production equipment.				
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.				
K All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.)				
Fipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-				
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well				
location, except for utility's distribution infrastructure.				
When all work has been completed, return this form to the appropriate District office to schedule an inspection.				
signature 04 64 TITLE C	ONST. SPECIA	ust	DATE 5/1/19	
TYPE OR PRINT NAME REX ULAICH E-MAIL:	REX_ULRICH (DOKY. COM	PHONE: 806-215-7135	
APPROVED BY: New Fint TITLE Compliance Office ADATE 8-27-19				

-

•

Casillas, Bertha, EMNRD


From:	Fortner, Kerry, EMNRD
Sent:	Thursday, May 2, 2019 2:41 PM
То:	Casillas, Bertha, EMNRD
Subject:	FW: NHU 28-311 P&A
Attachments:	28-311.3.pdf

Can I get color copies please?

From: Ulrich, Rex B <Rex_Ulrich@oxy.com> Sent: Wednesday, May 1, 2019 9:50 AM To: Fortner, Kerry, EMNRD <Kerry.Fortner@state.nm.us> Cc: Restrepo, Carlos E <Carlos_Restrepo@oxy.com>; Perry, Jake A <Jake_Perry@oxy.com> Subject: [EXT] NHU 28-311 P&A


Kerry,

Below ground marker has been installed on NHU 28-311 and is ready for your inspection prior to backfill. Thanks, Rex



.

2



Rex Ulrích CONSTRUCTION SPECIALIST OXY PERMIAN, LTD. (806) 215-7135 Cell rex_ulrich@oxy.com

Cheap labor is not skilled... Skilled labor is not cheap

3