

HOBBS OCD
AUG 20 2019

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name OWL		API Number 30-025-09806	
Property Name MARALO Sholes B		Well No. # 2	

1. Surface Location

UL - Lot P	Section 25	Township 25S	Range 36E	Feet from 660	N/S Line S	Feet From 660	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR INJ ☐ SWD ☒	PRODUCER OIL ☐ GAS ☐	DATE 8-14-19
--	--	--	---	------------------------

OBSERVED DATA

	(A) Surface	(B) Intern(1)	(C) Intern(2)	(D) Prod Casing	(E) Tubing
Pressure	0	0	N/A	0	220
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for water-flood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Jose Cerrillo</i>	OIL CONSERVATION DIVISION
Printed name: Jose Cerrillo	Entered into RBDMS
Title: Field Supervisor	Re-test <i>[Signature]</i>
E-mail Address:	
Date: 8-14-2019	Phone:
Witness: <i>Gary Rotenberry</i>	

INSTRUCTIONS ON BACK OF THIS FORM