

Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

SEP 04 2019

BRADENHEAD TEST REPORT

RECEIVED

Operator Name SAHARA OPERATING Co		API Number 30025249080000	
Property Name NORTH ELMAR UNIT		Well No. 58	

Surface Location									
UL - Lot D	Section 36	Township 26	Range 32		Feet from 770	N/S Line N	Feet from 990	E/W Line W	County LEA


Well Status												
☒ YES	TA'D WELL	NO	☒ YES	SHUT-IN	NO	INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE Aug 28, 2019

OBSERVED DATA

	(A)Surface	(B)Interm1	(C)Interm2	(D)Prod Csg	(E)Tubing
Pressure	0			0	No TBS
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected or waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

SURFACE ABOUT A 2 SECOND PUFF DOWN TO NOTHING

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Robert McAlpine		Entered into RBDMS	
Title: President		Re-test: 	
E-mail Address: Rob@SAHARAOPER.COM			
Date: 8-29-2019	Phone: 432-697-0967		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM