

HOBBS OCD

AUG 12 2019

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEVRON	API Number 30-025-12334
Property Name WDDU	Well No. 072

Surface Location

UL - Lot M	Section 33	Township 24S	Range 30E	Feet from 330	N/S Line S	Feet from 660	E/W Line W	County LEE
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR ☒ INJ	SWD	OIL PRODUCER OIL ☐ GAS ☐	DATE 7/1/2019
--	--	--	-----	---	-------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	0		0	1300
Flow Characteristics					
Pull	Y	Y	Y / N	Y / N	CO2 ☐
Steady Flow	Y	Y	Y / N	Y / N	WTR ☐
Surges	Y	Y	Y / N	Y / N	GAS ☐
Down to nothing	Y	Y	Y / N	Y / N	Type of Fluid
Gas or Oil	Y	Y	Y / N	Y / N	Injected for
Water	Y	Y	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

7/1 Need tok. for Prod. csg.
7/2 back track UICN

Signature:	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date:	Phone:
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM