

HOBBS OCD

AUG 12 2019

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHEVRON	API Number 30-025-31487
Property Name WDDU	Well No. 120

Surface Location

UL - Lot F	Section 32	Township 24S	Range 38E	Feet from 2190	N/S Line N	Feet From 2224	E/W Line W	County LEE
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

PROD WELL ☒ YES	NO	SHUT-IN ☒ YES	NO	INJECTOR ☒ INJ	SWD	OIL	PRODUCER	GAS	DATE 7/1/2019
--	----	--	----	---	-----	-----	----------	-----	-------------------------

OBSERVED DATA

	(A) Surface	(B) Interm (1)	(C) Interm (2)	(D) Prod Casing	(E) Tubing
Pressure	0			0	NONE
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☐
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of fluid injected for waterflood if applicable
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date:	Phone:
Witness: Harry Coleman	

INSTRUCTIONS ON BACK OF THIS FORM