

HOBBS OCD

AUG 12 2019

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON	API Number 30-025-34994
Property Name WDDU	Well No. 114

Surface Location

UL - Lot C	Section 5	Township 25S	Range 38E	Feet from 108	N/S Line N	Feet From 2325	E/W Line W	County LEE
----------------------	---------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	☒ INJ	SWD	OIL	PRODUCER	GAS	DATE 7/1/2019
------------------	-------------------------------------	----------------	-------------------------------------	--------------------------------------	-----	-----	----------	-----	-------------------------

OBSERVED DATA

	(A) Surface	(B) Interm (1)	(C) Interm (2)	(D) Prod Csg	(E) Tubing
Pressure	0			0	1400
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR —
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

7/1 Had truck for prod. csg. —
7/2 vac truck used —

Signature:	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date:	Phone:
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM