

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

REC'D/MIDLAND

JUL 24 2019

HOBBS OCE

AUG 22 2019

BRADENHEAD TEST REPORT

RECEIVED	Operator Name XTO Energy, Inc	API Number 30-025-28923
	Property Name Seven Rivers Queen Waterflood, North	Well No. 10

2. Surface Location

UL - Lot F	Section 4	Township 22S	Range 36E		Feet from 2623	N/S Line North	Feet From 1330	E/W Line West	County Lea
---------------	--------------	-----------------	--------------	--	-------------------	-------------------	-------------------	------------------	---------------



Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR INJ	PRODUCER OIL	GAS	DATE 4-16-19
------------------	----------------	-----------------	-----------------	-----	-----------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	0	N/A	0	0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 — WTR ✓ GAS —
Steady Flow	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applies.
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks — Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: Kevin Mark Burt	Entered into RBDMS
Title: Lease Operator	Re-test
E-mail Address: kevin-burt@xtoenergy.com	
Date: 4-16-19	
Phone: 575-441-1639	
Witness:	