

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

REC'D/MIDLAND

JUL 24 2019

AUG 22 2019

BRADENHEAD TEST REPORT

RECEIVED	Operator Name XTO Energy, Inc	API Number 30-025-28926
	Property Name Seven Rivers Queen Waterflood, North	Well No. 13

7. Surface Location

UL - Lot K	Section 4	Township 22S	Range 36E		Feet from 1325	N/S Line South	Feet From 1330	E/W Line West	County Lea
---------------	--------------	-----------------	--------------	--	-------------------	-------------------	-------------------	------------------	---------------



Well Status

TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	☒ INJ	INJECTOR SWD	OIL PRODUCER	GAS	DATE 4-16-19
------------------	-------------------------------------	----------------	-------------------------------------	--------------------------------------	-----------------	-----------------	-----	-----------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	N/A	N/A	0	0
Flow Characteristics					
Puff	Y / ☒ N	Y / N	Y / N	Y / ☒ N	CO2 —
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	WTR ☒
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS —
Down to nothing	☒ Y / N	Y / N	Y / N	☒ Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: Kevin Mark Burt	Entered into RBDMS
Title: Lease Operator	Re-test 
E-mail Address: kevin-burt@xtowenergy.com	
Date: 4-16-19	
Phone: 575-441-1639	
Witness:	