

HOBBS OCD

AUG 22 2019

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

REC'D/MIDLAND

JUL 24 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name XTO Energy, Inc	API Number 30-025-04592
Property Name Eunice Monument South Unit	Well No. 344

7. Surface Location

UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
N	10	21S	36E		660	South	1980	West	Lea

Well Status

TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	☒ INJ	INJECTOR SWD	PRODUCER OIL	GAS	DATE 07-20-19
------------------	-------------------------------------	----------------	-------------------------------------	--------------------------------------	-----------------	-----------------	-----	------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csing	(E) Tubing
Pressure	0	0	N/A	0	0
Flow Characteristics					
Puff	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	CO2 ☒
Steady Flow	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	WTR ☒
Surges	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	GAS ☒
Down to nothing	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	
Water	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Lorenzo Calvez</i>	OIL CONSERVATION DIVISION
Printed name: Lorenzo Calvez	Entered into RBDMS
Title: Lease Operator	Re-test <i>X 7</i>
E-mail Address: Lorenzo.Calvez@XTO Energy.com	
Date: 07-20-19	
Phone: 575-390-5995	
Witness:	