

REC'D/MIDLAND

JUL 24 2019

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

AUG 22 2019 RECEIVED	Operator Name XTO Energy, Inc	API Number 30-025-04605
	Property Name Eunice Monument South Unit	Well No. 314

7. Surface Location

UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
L	11	21S	36E		1980	South	660	West	Lea

Well Status

TA'D WELL YES	<input checked="" type="radio"/> NO	SHUT-IN YES	<input checked="" type="radio"/> NO	INJECTOR <input checked="" type="radio"/> INJ	SWD	PRODUCER OIL	GAS	DATE 7-20-19
------------------	-------------------------------------	----------------	-------------------------------------	--	-----	-----------------	-----	-----------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	0	0	0	360
Flow Characteristics					
Puff	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	CO2 <input type="checkbox"/>
Steady Flow	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	WTR <input checked="" type="checkbox"/>
Surges	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	GAS <input type="checkbox"/>
Down to nothing	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	
Water	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y <input checked="" type="radio"/> N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Lorenzo Galvez</i>	OIL CONSERVATION DIVISION
Printed name: Lorenzo Galvez	Entered into RBDMS
Title: Lease Operator	Re-test
E-mail Address: Lorenzo.Galvez@XTOEnergy.com	<i>X 7</i>
Date: 07-20-19	
Phone: 575-390-5995	
Witness:	