

HOBBS OCD
SEP 16 2019
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name STRAND ENGINEERING	*API Number 30-028-24048
Property Name NEW MEXICO DK STATE COMM	Well No. #001

Surface Location									
UL - Lot F	Section 18	Township 17S	Range 3SE	Feet from 1980	N/S Line N	Feet from 1964	E/W Line N	County LEA	

Well Status									
YES	TA'D WELL NO	YES	SHUT-IN NO	INJECTOR INJ	SWD	OIL	PRODUCER GAS	DATE 8/30/2019	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0	0	0	300
Flow Characteristics	0	0	0	0	
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS ✓
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood If
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

24 hr Shut in on all casing and Tubing
Bradenhead Test
Compressor Pumping Pressure on Tubing to unload
& keep well unloaded, Have 1/4 tubing inside 2 3/8 tubing
unloading & throw 1/4 tubing Pumping Pressure on 2 3/8 tubing to unload well

Signature: <i>J. Brewer</i>	OIL CONSERVATION DIVISION
Printed name: Jackie Brewer	Entered into RBDMS
Title: Pumper	Re-test
E-mail Address: brewer212@aol.com	<i>X</i>
Date: 8/30/2019	
Phone: 575 840 7560	
Witness:	