

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

JUN 24 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-05491
Property Name NORTH HOBBS (G/SA) UNIT	Well No. 111

7. Surface Location

UL - Lot D	Section 25	Township 18-S	Range 37-E	Feet from 660	N/S Line NORTH	Feet From 660	E/W Line WEST	County LEA
---------------	---------------	------------------	---------------	------------------	-------------------	------------------	------------------	---------------

Well Status

Well Status	SHUT-IN No	PRODUCING INT	DATE 6-11-19
-------------	---------------	------------------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	1085
Flow Characteristics					
Puff	Y / (N)	Y / N	Y / N	(Y) / N	
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	
Surges	Y / (N)	Y / N	Y / N	Y / (N)	
Down to nothing	Y / (N)	Y / N	Y / N	(Y) / N	
Gas or Oil	Y / (N)	Y / N	Y / N	(Y) / N	
Water	Y / (N)	Y / N	Y / N	Y / (N)	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME — WTR, GAS, CO2

Rate - 1795 bwpd

(A) Had 0 pressure.

(D) Had a puff of gas.

Bryan Caplin
575-441-9139
6-11-19

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date: JUN 18 2019	Phone: 806-592-6280
Witness:	