

HOBBS OCD

State of New Mexico

JUL 12 2019 Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name EOR OPERATING COMPANY		API Number 30-041-00087	
Property Name MILNESAND UNIT		Well No. 36	

Surface Location

UL - Lot N	Section 18	Township 8S	Range 35E	Feet from 660	N/S Line S	Feet From 1980	E/W Line W	County ROOSEVELT
---------------	---------------	----------------	--------------	------------------	---------------	-------------------	---------------	---------------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR INJ	PRODUCER OIL	GAS	DATE 3/27/2019
------------------	----------------	-----------------	-----------------	-----	-------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		0	500
Flow Characteristics					
Puff	Y / (N)	Y / (N)	Y / N	Y / (N)	CO2 —
Steady Flow	Y / (N)	Y / (N)	Y / N	Y / (N)	WTR —
Surges	Y / (N)	Y / (N)	Y / N	Y / (N)	GAS —
Down to nothing	(Y) / N	(Y) / N	Y / N	(Y) / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / (N)	Y / (N)	Y / N	Y / (N)	
Water	Y / (N)	Y / (N)	Y / N	Y / (N)	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Barry Broussard</i>		OIL CONSERVATION DIVISION	
Printed name: <i>Barry Broussard</i>		Entered into RBDMS	
Title: <i>Field REA</i>		Re-test	
E-mail Address: <i>Barry Broussard @ BELL SOUTH.NET</i>			
Date: <i>3/27/2019</i>	Phone: <i>337-254-7887</i>		
Witness:			