

HOBBS OCD
JUL 12 2019
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name EOR OPERATING COMPANY	API Number 30-041-00029
Property Name MILNESAND UNIT	Well No. 122

Surface Location

UL - Lot N	Section 7	Township 8S	Range 35E	Feet from 660	N/S Line S	Feet From 1980	E/W Line W	County ROOSEVELT
---------------	--------------	----------------	--------------	------------------	---------------	-------------------	---------------	---------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ INJ	SWD	PRODUCER OIL	GAS	DATE 3/27/2019
--	--	--	-----	-----------------	-----	-------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0	0		0	750
Flow Characteristics					
Puff	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	CO2 —
Steady Flow	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	WTR —
Surges	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	GAS —
Down to nothing	☒ Y / N	☒ Y / N	Y / N	☒ Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Barry Broussard</i>	OIL CONSERVATION DIVISION
Printed name: <i>Barry Broussard</i>	Entered into RBDMS
Title: <i>Field REP</i>	Re-test
E-mail Address: <i>Barry.Broussard@BELLISOUTH.NET</i>	
Date: <i>3/27/2019</i>	
Phone: <i>337-254-7887</i>	
Witness:	