

HOBBS OCD

JUL 12 2019

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name EOR OPERATING COMPANY		API Number 30-041-00251
Property Name MILNESAND UNIT		Well No. 54

7. Surface Location

UL - Lot H	Section 13	Township 8S	Range 34E	Feet from 2050	N/S Line N	Feet From 660	E/W Line E	County ROOSEVELT
---------------	---------------	----------------	--------------	-------------------	---------------	------------------	---------------	---------------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR INJ	PRODUCER OIL	GAS	DATE 3/27/2019
------------------	----------------	-----------------	-----------------	-----	-------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		0	600
Flow Characteristics					
Puff	Y / (N)	Y / (N)	Y / N	Y / (N)	CO2 —
Steady Flow	Y / (N)	Y / (N)	Y / N	Y / (N)	WTR —
Surges	Y / (N)	Y / (N)	Y / N	Y / (N)	GAS —
Down to nothing	(Y) / N	(Y) / N	Y / N	(Y) / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / (N)	Y / (N)	Y / N	Y / (N)	
Water	Y / (N)	Y / (N)	Y / N	Y / (N)	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Barry Broussard</i>		OIL CONSERVATION DIVISION	
Printed name: <i>Barry Broussard</i>		Entered into RBDMS	
Title: <i>FIELD REP</i>		Re-test	
E-mail Address: <i>Barry.Broussard@BELL SOUTH.NET</i>			
Date: <i>3/27/2019</i>	Phone: <i>337-254-2887</i>		
Witness:			