

HOBBS OCD
JUL 12 2019

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name EOR OPERATING COMPANY		API Number 30-041-00256
Property Name MILNESAND UNIT		Well No. 59

7. Surface Location

UL - Lot B	Section 13	Township 8S	Range 34E	Feet from 660	N/S Line N	Feet From 1980	E/W Line E	County ROOSEVELT
---------------	---------------	----------------	--------------	------------------	---------------	-------------------	---------------	---------------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR NO	SWD	PRODUCER OIL	GAS	DATE 3/27/2019
------------------	----------------	----------------	-----	-----------------	-----	-------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		0	200
Flow Characteristics					
Puff	Y / (N)	Y / (N)	Y / N	Y / (N)	CO2 —
Steady Flow	Y / (N)	Y / (N)	Y / N	Y / (N)	WTR —
Surges	Y / (N)	Y / (N)	Y / N	Y / (N)	GAS —
Down to nothing	(Y) N	(Y) N	Y / N	(Y) N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / (N)	Y / (N)	Y / N	Y / (N)	
Water	Y / (N)	Y / (N)	Y / N	Y / (N)	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Barry Broussard</i>		OIL CONSERVATION DIVISION	
Printed name: Barry Broussard		Entered into RBDMS	
Title: FIELD REP		Re-test	
E-mail Address: Barry.Broussard@REBIL SOUTH.NET			
Date: 3/27/2019	Phone: 337-254-7887		
Witness:			