

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name EOR OPERATING COMPANY		API Number 30-041-10147
Property Name MILNESAND UNIT		Well No. 24

2. Surface Location

UL - Lot J	Section 19	Township 8S	Range 35E	Feet from 1980	N/S Line S	Feet From 1980	E/W Line E	County ROOSEVELT
---------------	---------------	----------------	--------------	-------------------	---------------	-------------------	---------------	---------------------

Well Status

TA'D WELL YES	☒ NO	☒ YES	SHUT-IN NO	INJECTOR INJ	PRODUCER SWD	OIL	GAS	DATE 3/27/2019
------------------	-------------------------------------	--------------------------------------	---------------	-----------------	-----------------	-----	-----	-------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	○			○	○
Flow Characteristics					
Puff	Y / ☒ N	Y / N	Y / N	Y / ☒ N	CO2 —
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	WTR —
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS —
Down to nothing	☒ Y / N	Y / N	Y / N	☒ Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Barry Broussard</i>		OIL CONSERVATION DIVISION
Printed name: <i>Barry Broussard</i>		Entered into RBDMS
Title: <i>FIELD REP</i>		Re-test
E-mail Address: <i>Barry Broussard</i>		
Date: <i>3/27/2019</i>	Phone: <i>337-254-7887</i>	
Witness:		