

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD
SEP 10 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name GP II Energy		API Number 30-025-10334
Property Name N. Mexico m ST.		Well No. #12

1. Surface Location

UL - Lot M	Section 17	Township 22S	Range 37E	Feet from 660	N/S Line S	Feet From 660	E/W Line W	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR INJ	SWD	PRODUCER ☒ OIL	GAS	DATE 8-27-19
--	--	-----------------	-----	--	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Intern(1)	(C) Intern(2)	(D) Prod Csg	(E) Tubing
Pressure	0	N/A	N/A	35	200
Flow Characteristics					
Pull	Y	N	Y	N	CO2 ☐
Steady Flow	Y	N	Y	N	WTR ☐
Surges	Y	N	Y	N	GAS ☐
Down to nothing	Y	N	Y	N	Type of fluid Injected for Water/Gel if applies
Gas or Oil	Y	N	Y	N	
Water	Y	N	Y	N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Dillard Barrick	OIL CONSERVATION DIVISION
Printed name: Dillard Barrick	Entered into RBDMS
Title: Pumper	Re-test
E-mail Address: dillardob@wsttx.net	
Date: 8-27-19	Phone: 432-210-4958
Witness: Jim Hansen	

INSTRUCTIONS ON BACK OF THIS FORM