

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD
SEP 19 2019
RECEIVED

BRADENHEAD TEST REPORT

Operator Name GP II Energy		API Number 30-025-10361
Property Name N. Mexico m ST.		Well No. #11

1. Surface Location

UL - Lot J	Section 19	Township 22S	Range 37E	Feet from 1980	N/S Line S	Feet From 1980	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	INJ	SWD	☒ OIL	PRODUCER GAS	DATE 8-27-19
------------------	-------------------------------------	----------------	-------------------------------------	-----	-----	--------------------------------------	-----------------	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	N/A	N/A	25	25
Flow Characteristics					
Pull	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	CO2 ☐
Steady Flow	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	WTR ☐
Surges	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	GAS ☐
Down to nothing	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	
Water	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Dillard Barrick	OIL CONSERVATION DIVISION
Printed name: Dillard Barrick	Entered into RBDMS ☒
Title: Pumper	Re-test ☒
E-mail Address: dillard.b@wstx-net	
Date: 8-27-19	Phone: 432-210-4958
Witness: Shay Johnson	

INSTRUCTIONS ON BACK OF THIS FORM