

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD
SEP 19 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name BP II Energy		API Number 30-025-10363
Property Name N. Mexico m ST.		Well No. #24

Surface Location

UL - Lot 0	Section 19	Township 22S	Range 37E	Feet from 660	N/S Line S	Feet from 1980	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN NO ☐ INJ ☒	INJECTOR SWD ☐	PRODUCER OIL ☐ GAS ☐	DATE 8-27-19
--	--	---------------------------------------	---	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm (1)	(C) Interm (2)	(D) Prod Csg	(E) Tubing
Pressure	0	N/A	N/A	0	VAC
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid Injected for Waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Oil MIT Failed MIT - Lost 95# in 30 min.

Signature: Dillard Barrick	OIL CONSERVATION DIVISION
Printed name: Dillard Barrick	Entered into RBDMS [Signature]
Title: Pumper	Re-test: [Signature]
E-mail Address: dillard.b@wstx.net	
Date: 8-27-19	Phone: 438-240-4958
Witness: Ray Robinson	

INSTRUCTIONS ON BACK OF THIS FORM