

HOBBS OCD

SEP 19 2019

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CP II Energy		API Number 30-025-10515	
Property Name N. Mexico m ST.		Well No. #25	

1. Surface Location

UL - Lot L	Section 29	Township 22S	Range 37E	Feet from 1980	N/S Line S	Feet from 660	E/W Line E.W	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	------------------------	----------------------

Well Status

PROD WELL ☒ YES ☐ NO	SHUT-IN ☐ YES ☐ NO	INJECTOR ☒ INJ ☐ SWD	PRODUCER ☐ OIL ☐ GAS	DATE 8-27-19
--	---	--	---	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm (1)	(C) Interm (2)	(D) Prod Csg	(E) Tubing
Pressure	N/A	N/A	N/A	0	?
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☐
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Maximum if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Looks T/A'd - Tbg stuck and csg (~~bleed down~~)
No record of work on well.
Failure - Rule: 19.15.26.11

Signature: Dillard Barnick		OIL CONSERVATION DIVISION	
Printed name: Dillard Barnick		Entered into RBDMS	
Title: Pumper		Re-test	
E-mail Address: Dillardb@wstx.net			
Date: 9-12-19	Phone: 432-210-4958		
Witness: Sam Palmer			

INSTRUCTIONS ON BACK OF THIS FORM