

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

SEP 19 2019

BRADENHEAD TEST REPORT

RECEIVED

Operator Name GP II Energy		API Number 30-025-10519	
Property Name N. Mexico m st.		Well No. #9	

Surface Location

UL - Lot m	Section 30	Township 22S	Range 37E	Feet from 660	N/S Line S	Feet from 660	E/W Line W	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ	INJECTOR SWD	OIL	PRODUCER GAS	DATE 8-27-19
------------------	-----------	----------------	-----------	-----	-----------------	------------	-----------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Intern(1)	(C)Intern(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	25	25
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ___
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ___
Surges	Y/N	Y/N	Y/N	Y/N	GAS ___
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid Injured for Wash fluid if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Dillard Barrick		OIL CONSERVATION DIVISION	
Printed name: DILLARD BARRICK		Entered into RBDMS	
Title: Pumper		Re-test	
E-mail Address: dillard.b@wstx.net			
Date: 9-13-19	Phone: 432-210-4958		
432-653-3555	Witness: Dan Robinson		

INSTRUCTIONS ON BACK OF THIS FORM