

HOBBS OCD

SEP 19 2019

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name GP II Energy		API Number 30-025-23428
Property Name N. Mexico m ST.		Well No. # 63

1. Surface Location

UL - Lot H	Section 30	Township 23	Range 37E	Feet from 2540	N/S Line N	Feet From 1280	E/W Line E	County LEA
----------------------	----------------------	-----------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ	SWD	OIL	PRODUCER GAS	DATE 8-27-19
------------------	-----------	----------------	-----------	-----	-----	------------	-----------------	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	N/A	N/A	20	20
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid Injected for Waterflood if applicable
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Dillard Barrick	OIL CONSERVATION DIVISION
Printed name: Dillard Barrick	Entered into RBDMS
Title: Pumper	Re-test [Signature]
E-mail Address: dillardob@wstx.net	
Date: 8-27-19	Phone: 432-210-4958
Witness: Shay Helenoson	

INSTRUCTIONS ON BACK OF THIS FORM