

HOBBS OCD State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BOVA HEAD TEST REPORT

GP II Energy		API Number 30-025-23922	
N. Mexico M ST.		Well No. 472	

1. Surface Location

UL - Lot J	Section 20	Township 22S	Range 37E	Feet from 2810	N/S Line S	Feet From 1750	E/W Line E	County LEA
---------------	---------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJ NO	INJECTOR SWD	PRODUCER OIL	GAS	DATE 8-27-19
------------------	----------------	-----------	-----------------	-----------------	-----	-----------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	30	N/A	N/A	25	25
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood if applicable
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Surface csg. bleed down - in / min.

Signature: Dillard Barrick	OIL CONSERVATION DIVISION
Printed name: Dillard Barrick	Entered into RBDMS
Title: Pumper	Re-test
E-mail Address: dillardb@wsttx.net	
Date: 9-12-19	
Phone: 432-210-4958	
Witness: Gary Johnson	

INSTRUCTIONS ON BACK OF THIS FORM