

HOBBS OCD

SEP 19 2019

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

GP II RECEIVED Energy		Operator Name	API Number
N. Mexico M ST.			30-025-24251
Property Name		Well No.	
		# 81	

Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	EAV Line	County
G	30	20S	37E	2440	N	2550	E	LEA

Well Status

TA'D WELL	YES	NO	SHUT-IN	YES	NO	INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE
												8-27-19

OBSERVED DATA

	(A) Surface	(B) Intermt (1)	(C) Intermt (2)	(D) Prod Csg	(E) Tubing
Pressure	0	N/A	N/A	20	20
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ___
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ___
Surges	Y/N	Y/N	Y/N	Y/N	GAS ___
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid Inferred for Water/Gas if applies.
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Dillard Barrick</i>	OIL CONSERVATION DIVISION
Printed name: <i>DILLARD BARRICK</i>	Entered into RBDMS
Title: <i>Pumper</i>	Re-test
E-mail Address: <i>dillardob@wstx.net</i>	
Date: <i>9-13-19</i>	Phone: <i>432-210-4958</i>
<i>432-653-2555</i>	Witness: <i>Ray Robinson</i>

INSTRUCTIONS ON BACK OF THIS FORM