

HOBBS OCD

SEP 19 2019

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name G P II Energy		API Number 30-025-24256	
Property Name N. Mexico m ST.		Well No. #67	

Surface Location

UL - Lot I	Section 30	Township 22S	Range 37E	Feet from 1406	N/S Line S	Feet From 1262	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJ INJECTOR INJ ☐ SWD ☐	OIL PRODUCER ☒ GAS ☐	DATE 8-27-19
--	--	---	--	------------------------

OBSERVED DATA

	(A) Surface	(B) Intern(1)	(C) Intern(2)	(D) Prod Csg	(E) Tubing
Pressure	0	N/A	N/A	25	25
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Dillard Barrick		OIL CONSERVATION DIVISION	
Printed name: DILLARD BARRICK		Entered into RBDMS	
Title: Pumper		Re-test ☒	
E-mail Address: dillardab@wstr.net			
Date: 9-13-19	Phone: 432-210-058		
432-653-3555	Witness: Shay Holman		

INSTRUCTIONS ON BACK OF THIS FORM