

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

SEP 19 2019

BRADENHEAD TEST REPORT

RECEIVED		Operator Name GP II Energy	API Number 30-025-24300
Property Name N. Mexico m ST.		Well No. #69	

Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
2	29	22S	37E	1360	S	1220	W	LEA

Well Status

YES	TA'D WELL NO	YES	SHUT-IN NO	INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 8-27-19
-----	------------------------	-----	----------------------	-----	----------	-----	------------	----------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Intern(1)	(C) Intern(2)	(D) Prod Csg	(E) Tubing
Pressure	20	NA	NA	25	25
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for analysis if applicable
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Surface csg. blew down in. 3 min.

Signature: Dillard Barrick	OIL CONSERVATION DIVISION
Printed name: Dillard Barrick	Entered into RBDMS
Title: Pumper	Re-test [Signature]
E-mail Address: dillarb@wsf.net	
Date: 9-12-19	Phone: 432-210-4958
Witness: Dan Robinson	

INSTRUCTIONS ON BACK OF THIS FORM