

HOBBS OCD

SEP 19 2019

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name GP II Energy		API Number 30-025-24512	
Property Name N. Mexico m ST.		Well No. # 76	

1. Surface Location

UL - Lot 0	Section 30	Township 23S	Range 37E	Feet from 100	N/S Line S	Feet From 1400	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJ	INJECTOR SWD	☒ OIL	PRODUCER GAS	DATE 8-27-19
--	--	-----	-----------------	--------------------------------------	-----------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm1	(C)Interm2	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	20	20
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Wellhead if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Dillard Garrick		OIL CONSERVATION DIVISION	
Printed name: DILLARD BARRICK		Entered into RBDMS	
Title: Pumper		Re-test ygl	
E-mail Address: dillard-b@WSTX.NET			
Date: 9-13-19	Phone: 432-210 4958		
432-653-3555	Witness: Guy Robinson		

INSTRUCTIONS ON BACK OF THIS FORM