

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Seely Oil Company		*API Number 30025277590000
Property Name EK Penrose Sand Unit		Well No. 401

Surface Location									
UL - Lot K	Section 30	Township 18S	Range 34E		Feet from 1980	N/S Line S	Feet From 1830	E/W Line W	County Lea

Well Status									
TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	INJECTOR ☒ INJ	SWD	PRODUCER OIL	GAS	DATE 9-12-19	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	1350
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

HOBBS CO
SEP 19 2019
RECEIVED

Signature: Mike Frazier		OIL CONSERVATION DIVISION
Printed name: Mike Frazier		Entered into RBDMS
Title: Pumper		Re-test
E-mail Address: nitro mikey @ my wdo . com		
Date:	Phone:	
Witness: Greg Robinson		

INSTRUCTIONS ON BACK OF THIS FORM