

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

SEP 20 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron USA Inc	API Number 36-025-22841
Property Name Quail Queen Unit	Well No. 012

1. Surface Location

UL - Lot 6G	Section 11	Township 19S	Range 34E	Feet from 1980	Line 1980	Feet from 1980	Line 1980	County Lee
-----------------------	----------------------	------------------------	---------------------	--------------------------	---------------------	--------------------------	---------------------	----------------------

Well Status

☒ YES TA'D WELL NO	☒ YES SHUT-IN NO	☒ INJ INJECTOR SWD	OIL PRODUCER GAS	DATE 4-17-19
--	--	--	------------------	------------------------

OBSERVED DATA

	(A) Surface	(B) Intern(1)	(C) Intern(2)	(D) Prod Cmg	(E) Tubing
Pressure	0	NA	NA	0	
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 WTR ____ GAS ____ Type of fluid Entered for Waterflood if applies
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Bradley Bats	OIL CONSERVATION DIVISION
Printed name: Bradley Bats	Entered into RBDMS
Title: PS	Re-test
E-mail Address:	
Date: 9/5/19	Phone: 432-553-384
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM