

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

SEP 20 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron USA Inc		API Number 30-025-23031	
Property Name Quail Queen Unit		Well No. 008	

1. Surface Location

U/L - Lot K	Section 11	Township 19S	Range 34E	Feet from 2080	N/E Line N/E	Feet From 1980	E/W Line E/W	County Lee
----------------	---------------	-----------------	--------------	-------------------	-----------------	-------------------	-----------------	---------------

Well Status

TA'D WELL ☒ YES ☐ NO	SHUT-IN ☒ YES ☐ NO	INJECTOR ☒ INJ ☐ SWD	PRODUCER OIL ☐ GAS	DATE 4-17-19
--	--	--	---	-----------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	NA	NA	0	
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid expected for waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Braxton Batts</i>		OIL CONSERVATION DIVISION	
Printed name: Braxton Batts		Entered into RBDMS	
Title: PS		Re-test	
E-mail Address:			
Date: 9/5/19	Phone: 432-553-3184		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM