

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

SEP 20 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chvron USA Inc	API Number 20-25-26221
Property Name Quail Queen	Well No. 0034

1. Surface Location

UL - Lot T	Section 11	Township 19S	Range 34E	Feet from 1841	N/S Line 1841	Feet from 759	E/W Line Lee	County Lee
----------------------	----------------------	------------------------	---------------------	--------------------------	-------------------------	-------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ SWD	OIL SWD	PRODUCER GAS	DATE 4-7-19
-------------------------	----	-----------------------	----	-------------------	-------------------	------------------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csmg	(E)Tubing
Pressure	0	NA	NA	0	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 WTR GAS Type of fluid Entered for Waterflood if applies
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Brandon Butts	OIL CONSERVATION DIVISION
Printed name: Brandon Butts	Entered into RBDMS
Title: PS	Re-test
E-mail Address:	
Date: 9/5/19	Phone: 432-553-3124
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM