

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

HOBBS OCD

SEP 20 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron USA Inc		API Number 30-025-26707	
Property Name Quail Queen Unit		Well No. 011	

1. Surface Location

UL - Lot A	Section 11	Township 19S	Range 34E	Feet from 990	Line 0	Feet from 990	Line 0	County
----------------------	----------------------	------------------------	---------------------	-------------------------	------------------	-------------------------	------------------	--------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	PRODUCER OIL	GAS	DATE 4-17-19
------------------	----	----------------	----	------------------------	-----	-----------------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A			0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 WTR ____ GAS ____ Type of fluid injected for waterflood if applies
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Brandon Bat		OIL CONSERVATION DIVISION	
Printed name: Brandon Bat		Entered into RBDMS	
Title: PS		Re-test	
E-mail Address:			
Date: 9/5/19	Phone: 432-553-3184		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM