

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Seely Oil Company						*API Number 30025023470000			
Property Name EK Queen Unit								Well No. 024	
Surface Location									
UL - Lot K	Section 24	Township 18S	Range 33E		Feet from 2310	N/S Line S	Feet From 2310	E/W Line W	County Lea
Well Status									
TA'D WELL YES		SHUT-IN NO		INJECTOR INJ		PRODUCER OIL		DATE	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	300
Flow Characteristics					
Pull	Y	Y/N	Y/N	Y	CO2
Steady Flow	Y	Y/N	Y/N	Y	WTR
Surges	Y	Y/N	Y/N	Y	GAS
Down to nothing	Y	Y/N	Y/N	Y	Type of Fluid
Gas or Oil	Y	Y/N	Y/N	Y	Injected for
Water	Y	Y/N	Y/N	Y	Waterhead if

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

HOBBS OCD
SEP 19 2019
RECEIVED

Signature: Mike Frazier		OIL CONSERVATION DIVISION	
Printed name: Mike Frazier		Entered into RBDMS	
Title: Pumper		Re-test	
E-mail Address: nitromikey@mywdo.com			
Date:	Phone:		
Witness: Ray Robinson			

INSTRUCTIONS ON BACK OF THIS FORM