

HOBBS OGD

SEP 20 2019

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Clevon USA Inc		API Number 30-025-34788	
Property Name AAA New Mexico		Well No. EA STATE	

1. Surface Location

UL - Lot A	Section 24	Township 18 S	Range 37 E	Feet from 410	NS Line ☒	Feet from 610	EW Line ☒	County Lee
----------------------	----------------------	-------------------------	----------------------	-------------------------	--	-------------------------	--	----------------------

Well Status

TA'D WELL YES ☒	SHUT-IN YES ☒	INJ ☐	INJECTOR SWD ☐	PRODUCER ☒	GAS ☐	DATE 4/18/19
---	---	------------------------------	---------------------------------------	--	------------------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0			50	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of fluid subjected for waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature Braxton Bets		OIL CONSERVATION DIVISION	
Printed name. Braxton Bets		Entered into RBDMS	
Title PS		Re-test	
E-mail Address:			
Date 9/19/19	Phone 432-553-3104		
Witness			

INSTRUCTIONS ON BACK OF THIS FORM