

**HOBBS OCD**  
**JUL 23 2019**  
**RECEIVED**

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

**BRADENHEAD TEST REPORT**

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-05490
Property Name NORTH HOBBS (G/SA) UNIT	Well No. 341

**7. Surface Location**

UL - Lot O	Section 24	Township 18-S	Range 37-E	Feet from 330	N/S Line SOUTH	Feet From 2310	E/W Line EAST	County LEA
---------------	---------------	------------------	---------------	------------------	-------------------	-------------------	------------------	---------------

**Well Status**

Well Status	SHUT-IN NO	PRODUCING GIL	DATE 7-11-19
-------------	---------------	------------------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

**OBSERVED DATA**

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	G	N/A	340	431
<b>Flow Characteristics</b>					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME \_\_\_ WTR, \_\_\_ GAS, \_\_\_ CO2

(A) had a puff of gas  
(B) had a puff of gas

Bryan Lotlin  
575-441-9739  
7-11-19

Signature:	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date:	Phone: 806-592-6280
Witness:	